

**From:** [Catherine.Elizee](#)  
**To:** [Verline.marcellin@dpr.vi.gov](mailto:Verline.marcellin@dpr.vi.gov)  
**Cc:** [Buettner, Robert](#); [Patel, Harish](#); [Foley, Patrick](#); [Maria.Aloyo](#); [Craig.Miller](#); [Joyce.Wakefield](#)  
**Subject:** Opacity at East Incinerator stack on 5/6/21 - Notification  
**Date:** Thursday, May 6, 2021 9:20:14 AM  
**Attachments:** [image001.png](#)  
[image003.png](#)  
[image005.png](#)  
[image006.png](#)

---

Good morning Verline,

This morning we had an opacity at the East Incinerator stack intermittently from around 6:30am to 8:00am. We will follow up with a letter.

Thank you

**Catherine Elizee**

Environmental Superintendent


Limetree Bay Refining, LLC

Limetree Bay Terminals, LLC

O: 340-692-3073

[REDACTED]

1 Estate Hope | Christiansted, VI 00820-5652



---

**From:** Joyce.Wakefield <[JWakefield@lbenergy.com](mailto:JWakefield@lbenergy.com)>

**Sent:** Wednesday, May 5, 2021 10:12 PM

**To:** [Verline.marcellin@dpr.vi.gov](mailto:Verline.marcellin@dpr.vi.gov)

**Cc:** [Buettner.Robert@epa.gov](mailto:Buettner.Robert@epa.gov); [Patel.Harish@epa.gov](mailto:Patel.Harish@epa.gov); [foley.patrick@epa.gov](mailto:foley.patrick@epa.gov); [Maria.Aloyo@lbenergy.com](mailto:Maria.Aloyo@lbenergy.com); [Catherine.Elizee@lbenergy.com](mailto:Catherine.Elizee@lbenergy.com); [Craig.Miller@lbenergy.com](mailto:Craig.Miller@lbenergy.com)

**Subject:** H2S in Flare 8 Exceedance-Notification

Good Night Verline,

At 9 pm (5/5) we exceed the H2S limit of 162ppm 3-hr average on the 8 flare header.

Preliminary investigation shows that compressors at the #2 gas recovery unit tripped. The H2S is currently below the limit,

We will continue investigating and will follow-up with a letter. Please consider this our notification.

**Joyce Wakefield**

Environmental and Wildlife Specialist

Limetree Bay Refining & Terminals, LLC

O: 340-692-3205

[REDACTED]

1 Estate Hope | Christiansted, VI 00820-5652

